



MACHINES – COVENTRY SITE					
CNC MACHINES	All Axis Limits			Types	Spindles
Zayer 5000	X5000	Y2000	Z1800	Horizontal	50 INT
Wadkin	X3600	Y2150	Z1000	Gantry	50 INT
Correa	X5000	Y2000	Z900	Gantry	50 INT
Correa	X4000	Y1500	Z900	Gantry	50 INT
Devleig	X6800	Y2300	Z1300	Gantry	50 INT
CME	X2000	Y1000	Z1000	Vert/Hori	50 INT
Huron	X1600	Y800	Z1000	Vert/Hori	50 INT
Anayak	X3000	Y1000	Z900	Vert/Hori	50 INT
Elga	X3000	Y1000	Z900	Vert/Hori	50 INT
Arrow1500	X1500	Y700	Z700	Vertical	35 INT
Boko	X1000	X635	Z600	Vertical	35 INT
Zayer	X1750	Y900	Z950	Vert/Hori	50 int
Radial Drill					
Wire Eroder A	X500	Y400	Z250		
Wire Eroder b	X500	Y400	Z250		
FOBA Laser etch	X200	T100			
Lathe nc/manual	Z750	300			